

## ZKL BEARINGS PRICE LIST 2019

ZKL BEARINGS PRICE LIST 2019	
<a href="#">Franke66398L</a>	? 41.19
<a href="#">Franke68669A</a>	? 148.44
<a href="#">IMO11-20 0941/1-32162</a>	? 193.68
<a href="#">Franke66151L</a>	? 142.30
<a href="#">IMO12-25 1355/1-0326</a>	? 188.46
<a href="#">Franke68609A</a>	? 33.48
<a href="#">IMO90-20 0841/0-37052</a>	? 30.46
<a href="#">Franke68577A</a>	? 169.62
<a href="#">IMO92-20 0941/1-37262</a>	? 98.58
<a href="#">Franke77276B</a>	? 112.04
<a href="#">IMO92-20 0413/1-37212</a>	? 89.17
<a href="#">Franke73099L</a>	? 179.97
<a href="#">IMO11-25 1455/1-0317</a>	? 125.44
<a href="#">Liebherr A912 Li982706001</a>	? 103.28
<a href="#">Franke68653A</a>	? 39.68
<a href="#">IMO10-25 1255/0-0305</a>	? 91.61
<a href="#">Liebherr A922 Li982706001</a>	? 149.71
<a href="#">Franke66389L</a>	? 110.62
<a href="#">IMO10-20 0641/0-32032</a>	? 140.21
<a href="#">Liebherr R912 Li982706001</a>	? 129.53
<a href="#">Franke68753A</a>	? 78.41
<a href="#">IMO12-25 0755/1-0424</a>	? 50.23
<a href="#">Liebherr R922 Li982706001</a>	? 29.44
<a href="#">Franke77234B</a>	? 25.35
<a href="#">IMO10-25 1455/0-0307</a>	? 10.47
<a href="#">Liebherr R964982720001</a>	? 48.38
<a href="#">Franke75020A</a>	? 149.24
<a href="#">IMO12-25 0455/1-0421</a>	? 57.50
<a href="#">Liebherr R964B982720001</a>	? 109.89
<a href="#">Franke77278B</a>	? 35.24
<a href="#">IMO12-20 0311/1-32202</a>	? 138.60
<a href="#">Liebherr R964C982720001</a>	? 138.10
<a href="#">Franke66147L</a>	? 20.13
<a href="#">IMO11-25 1355/1-0316</a>	? 93.61
<a href="#">Liebherr R974982757401</a>	? 47.49
<a href="#">Franke68777A</a>	? 83.19
<a href="#">IMO12-25 0655/1-0423</a>	? 173.92
<a href="#">Liebherr R964 Li982811501</a>	? 56.01
<a href="#">Franke75060A</a>	? 160.17
<a href="#">IMO91-20 0741/1-37142</a>	? 98.23

<a href="#">Liebherr R964982811501</a>	? 72.76
<a href="#">Franke74140A</a>	? 42.25
<a href="#">IMO10-16 0400/0-0803</a>	? 102.58
<a href="#">Liebherr R964B982811501</a>	? 130.78
<a href="#">Franke68489A</a>	? 48.75
<a href="#">IMO10-16 0500/0-0804</a>	? 157.65
<a href="#">Liebherr R942 LI982855501</a>	? 180.41
<a href="#">Franke73107L</a>	? 21.56
<a href="#">IMO10-20 0541/0-32022</a>	? 13.74
<a href="#">Liebherr A308982882001</a>	? 73.23
<a href="#">Franke68801A</a>	? 29.26
<a href="#">IMO12-20 0941/1-32262</a>	? 42.15
<a href="#">Franke68647A</a>	? 30.48
<a href="#">IMO92-20 0541/1-37222</a>	? 56.56
<a href="#">Franke68582A</a>	? 134.51
<a href="#">IMO90-20 0941/0-37062</a>	? 197.10
<a href="#">Franke77284B</a>	? 101.44
<a href="#">IMO92-20 0841/1-37252</a>	? 19.23
<a href="#">Franke68655A</a>	? 76.29
<a href="#">IMO92-20 0641/1-37232</a>	? 59.42
<a href="#">Franke74122A</a>	? 164.85
<a href="#">IMO11-20 0641/1-32132</a>	? 65.94
<a href="#">Franke68735A</a>	? 198.90
<a href="#">IMO12-25 1455/1-0327</a>	? 8.24
<a href="#">Franke68965A</a>	? 161.63
<a href="#">IMO11-20 1091/1-32172</a>	? 98.85
<a href="#">Franke68953A</a>	? 176.30
<a href="#">IMO10-20 0741/0-32042</a>	? 115.11
<a href="#">Franke68681A</a>	? 107.59
<a href="#">IMO10-25 0855/0-0301</a>	? 96.47
<a href="#">Franke77295B</a>	? 198.25
<a href="#">IMO12-25 1155/1-0324</a>	? 191.92
<a href="#">Franke68633A</a>	? 94.21
<a href="#">IMO11-20 0741/1-32142</a>	? 76.92
<a href="#">Franke77254B</a>	? 130.39
<a href="#">IMO12-20 0841/1-32252</a>	? 190.37
<a href="#">Franke77248B</a>	? 17.71
<a href="#">IMO90-20 0413/0-37012</a>	? 103.95
<a href="#">Franke73087L</a>	? 41.31
<a href="#">IMO90-20 0541/0-37022</a>	? 115.81
<a href="#">Franke74098A</a>	? 156.41
<a href="#">IMO11-25 0755/1-0414</a>	? 62.17
<a href="#">Franke66162L</a>	? 106.27
<a href="#">IMO11-25 0555/1-0412</a>	? 65.32
<a href="#">Franke68665A</a>	? 155.17
<a href="#">IMO11-16 0500/1-0814</a>	? 87.09

<a href="#">Franke66399L</a>	? 57.59
<a href="#">IMO12-25 1255/1-0325</a>	? 163.87
<a href="#">Franke77305A</a>	? 73.52
<a href="#">IMO91-20 0311/1-37102</a>	? 153.24
<a href="#">Franke68631A</a>	? 194.70
<a href="#">IMO11-16 0100/1-081</a>	? 135.16
<a href="#">Franke73004L</a>	? 37.77
<a href="#">IMO91-20 0941/1-37162</a>	? 175.09
<a href="#">Franke68651A</a>	? 1.09
<a href="#">IMO12-20 0413/1-32212</a>	? 191.99
<a href="#">Franke75032A</a>	? 116.49
<a href="#">IMO90-20 0311/0-37002</a>	? 47.28
<a href="#">Franke73105L</a>	? 26.95
<a href="#">IMO10-20 0413/0-32012</a>	? 16.94
<a href="#">Franke73119L</a>	? 139.93
<a href="#">IMO10-20 0311/0-32002</a>	? 155.90
<a href="#">IMO11-25 0655/1-0413</a>	? 83.61
<a href="#">IMO10-25 1355/0-0306</a>	? 113.55
<a href="#">IMO10-20 0841/0-32052</a>	? 164.76
<a href="#">IMO10-20 1091/0-32072</a>	? 118.57
<a href="#">IMO12-25 0855/1-0321</a>	? 135.40
<a href="#">IMO10-25 0455/0-0401</a>	? 199.13
<a href="#">IMO12-20 0741/1-32242</a>	? 71.31
<a href="#">IMO11-25 0955/1-0312</a>	? 122.08
<a href="#">IMO12-20 0541/1-32222</a>	? 155.27
<a href="#">IMO91-20 0841/1-37152</a>	? 187.57
<a href="#">IMO10-25 1055/0-0303</a>	? 69.12
<a href="#">IMO11-25 0455/1-0411</a>	? 186.26
<a href="#">IMO90-20 0641/0-37032</a>	? 68.21
<a href="#">IMO11-16 0400/1-0813</a>	? 159.88
<a href="#">IMO10-25 0955/0-0302</a>	? 154.24
<a href="#">IMO91-20 0413/1-37112</a>	? 75.03
<a href="#">IMO10-25 0755/0-0404</a>	? 105.39
<a href="#">IMO92-20 0311/1-37202</a>	? 40.62
<a href="#">IMO10-25 1155/0-0304</a>	? 72.91
<a href="#">IMO90-20 1091/0-37072</a>	? 199.11
<a href="#">IMO11-25 1055/1-0313</a>	? 14.48
<a href="#">Franke68950A</a>	? 129.65
<a href="#">IMO11-25 1255/1-0315</a>	? 109.49
<a href="#">Franke68536A</a>	? 44.71
<a href="#">IMO12-20 0641/1-32232</a>	? 122.13
<a href="#">Franke68478A</a>	? 137.40
<a href="#">IMO91-20 0541/1-37122</a>	? 107.85
<a href="#">Franke74180A</a>	? 52.60
<a href="#">IMO11-25 0855/1-0311</a>	? 85.33
<a href="#">Franke68560A</a>	? 52.50

<a href="#">IMO92-20 1091/1-37272</a>	? 196.30
<a href="#">Franke77252A</a>	? 7.00
<a href="#">IMO90-20 0741/0-37042</a>	? 31.32
<a href="#">Franke68969A</a>	? 177.12
<a href="#">IMO11-20 0413/1-32112</a>	? 60.58
<a href="#">Franke75039A</a>	? 133.70
<a href="#">IMO10-16 0200/0-0801</a>	? 40.06
<a href="#">Franke75057A</a>	? 148.68
<a href="#">IMO12-25 0955/1-0322</a>	? 154.08
<a href="#">Franke77244A</a>	? 197.07
<a href="#">IMO92-20 0741/1-37242</a>	? 88.79
<a href="#">Franke68627A</a>	? 179.78
<a href="#">IMO91-20 1091/1-37172</a>	? 35.48
<a href="#">Franke75010A</a>	? 174.33
<a href="#">IMO12-25 0555/1-0422</a>	? 63.75
<a href="#">Franke68956A</a>	? 107.97
<a href="#">IMO11-25 1155/1-0314</a>	? 67.00
<a href="#">Franke74100A</a>	? 170.85
<a href="#">IMO12-25 1055/1-0323</a>	? 8.78
<a href="#">Franke68954A</a>	? 110.15
<a href="#">IMO10-25 0655/0-0403</a>	? 45.20
<a href="#">Franke77222A</a>	? 125.34
<a href="#">IMO11-16 0300/1-0812</a>	? 110.52
<a href="#">Franke67509A</a>	? 173.73
<a href="#">IMO10-16 0300/0-0802</a>	? 123.45
<a href="#">Franke68968A</a>	? 145.18
<a href="#">IMO10-20 0941/0-32062</a>	? 2.45
<a href="#">Franke73039L</a>	? 5.25
<a href="#">IMO12-20 1091/1-32272</a>	? 129.15
<a href="#">Franke68961A</a>	? 137.26
<a href="#">Franke67507A</a>	? 102.55
<a href="#">IMO10-25 0555/0-0402</a>	? 63.22
<a href="#">Franke75062A</a>	? 19.75
<a href="#">Franke75056A</a>	? 200.57
<a href="#">IMO11-20 0841/1-32152</a>	? 12.59
<a href="#">Franke75038A</a>	? 5.99
<a href="#">Franke68755A</a>	? 170.86
<a href="#">IMO91-20 0641/1-37132</a>	? 95.74
<a href="#">Franke68680A</a>	? 15.45
<a href="#">Franke68679A</a>	? 61.84
<a href="#">IMO11-20 0541/1-32122</a>	? 10.45
<a href="#">Standard 5161.45.2510.890.11.1503</a>	? 11.12
<a href="#">Rollix28 0941 01</a>	? 112.28
<a href="#">Standard 5161.45.2510.891.41.1503</a>	? 119.28
<a href="#">Rollix3 0980 02</a>	? 28.29
<a href="#">Standard 512.40.2622.400.11.1502</a>	? 149.13

<a href="#">Rollix8 0980 06</a>	? 46.15
<a href="#">Standard 512.40.2622.401.41.1502</a>	? 157.20
<a href="#">Rollix6 0980 09</a>	? 133.01
<a href="#">Standard 592.50.2644.990.41.1502</a>	? 134.07
<a href="#">Rollix33 0941 01</a>	? 180.28
<a href="#">Standard 5162.50.2660.891.41.1503</a>	? 83.28
<a href="#">Rollix36 0941 01</a>	? 72.82
<a href="#">Standard 5162.45.2654.890.11.1503</a>	? 112.46
<a href="#">Rollix39 0941 01</a>	? 195.13
<a href="#">Standard 5162.45.2654.891.41.1503</a>	? 15.64
<a href="#">Rollix31 0941 01</a>	? 10.88
<a href="#">Standard 512.35.2690.000.11.1503</a>	? 67.92
<a href="#">Rollix34 0941 01</a>	? 36.00
<a href="#">Standard 512.35.2690.001.41.1503</a>	? 41.84
<a href="#">Rollix37 0941 01</a>	? 179.79
<a href="#">Standard 5192.32.2800.990.41.1502</a>	? 45.92
<a href="#">Rollix2 105</a>	? 129.23
<a href="#">Standard 5192.40.2800.990.41.1502</a>	? 3.62
<a href="#">Rollix1 105</a>	? 1.43
<a href="#">Standard 511.40.2619.000.11.1502</a>	? 47.04
<a href="#">Rollix7 1075 01</a>	? 130.19
<a href="#">Standard 511.40.2619.001.41.1502</a>	? 60.56
<a href="#">Rollix7 1140 13</a>	? 177.44
<a href="#">Standard 5161.50.2660.891.41.1503</a>	? 94.73
<a href="#">Rollix23 1091 01</a>	? 185.67
<a href="#">Standard 5161.45.2654.890.11.1503</a>	? 133.88
<a href="#">Rollix26 1091 01</a>	? 67.59
<a href="#">Standard 5161.45.2654.891.41.1503</a>	? 15.14
<a href="#">Rollix29 1091 01</a>	? 92.10
<a href="#">Standard 561.50.2645.001.49.1504</a>	? 127.74
<a href="#">Rollix21 1091 01</a>	? 176.10
<a href="#">Standard 511.35.2620.000.11.1503</a>	? 175.89
<a href="#">Rollix24 1091 01</a>	? 141.89
<a href="#">Standard 511.35.2620.001.41.1503</a>	? 61.58
<a href="#">Rollix27 1091 01</a>	? 167.32
<a href="#">Standard 5162.50.2800.891.41.1503</a>	? 167.28
<a href="#">Rollix6 1116</a>	? 194.96
<a href="#">Standard 5191.25.2800.990.41.1502</a>	? 119.39
<a href="#">Rollix32 1091 01</a>	? 123.35
<a href="#">Standard 5192.25.2800.990.41.1502</a>	? 64.34
<a href="#">Rollix35 1091 01</a>	? 15.84
<a href="#">Standard 562.50.2800.001.49.1504</a>	? 37.00
<a href="#">Rollix38 1091 01</a>	? 8.29
<a href="#">Standard 592.50.2842.990.41.1502</a>	? 46.75
<a href="#">Rollix22 1091 01</a>	? 163.19
<a href="#">Standard 5191.40.2800.990.41.1502</a>	? 6.01

<a href="#">Rollix25 1091 01</a>	? 169.16
<a href="#">Standard 5191.32.2800.990.41.1502</a>	? 80.26
<a href="#">Rollix28 1091 01</a>	? 86.13
<a href="#">Standard 5161.50.2800.891.41.1503</a>	? 48.07
<a href="#">Rollix33 1091 01</a>	? 78.63
<a href="#">Standard 591.50.2842.990.41.1502</a>	? 163.55
<a href="#">Rollix36 1091 01</a>	? 61.78
<a href="#">Standard 511.40.2795.000.11.1502</a>	? 185.74
<a href="#">Rollix39 1091 01</a>	? 67.33
<a href="#">Standard 511.40.2795.001.41.1502</a>	? 75.61
<a href="#">Rollix31 1091 01</a>	? 156.16
<a href="#">Standard 512.40.2950.000.11.1502</a>	? 140.01
<a href="#">Rollix34 1091 01</a>	? 59.37
<a href="#">Standard 512.40.2950.001.41.1502</a>	? 92.16
<a href="#">Rollix37 1091 01</a>	? 178.84
<a href="#">Standard 512.45.2940.000.19.1502</a>	? 36.00
<a href="#">Rollix1 118</a>	? 192.11
<a href="#">Standard 512.45.2940.001.49.1502</a>	? 74.06
<a href="#">Rollix2 1225</a>	? 79.92
<a href="#">Standard 5162.50.3000.891.41.1503</a>	? 52.58
<a href="#">Rollix6 1250 21</a>	? 112.76
<a href="#">Standard 5192.50.3150.990.41.1502</a>	? 81.96
<a href="#">Rollix7 1304 04</a>	? 120.12
<a href="#">Standard 511.40.2915.000.11.1502</a>	? 115.64
<a href="#">Rollix2 1295</a>	? 187.30
<a href="#">Standard 511.40.2915.001.41.1502</a>	? 126.39
<a href="#">Rollix7 1385 03</a>	? 65.20
<a href="#">Standard 5192.40.3150.990.41.1502</a>	? 159.14
<a href="#">Rollix1 1295 01</a>	? 172.53
<a href="#">Standard 5161.50.3000.891.41.1503</a>	? 152.43
<a href="#">Rollix6 1390 03</a>	? 145.60
<a href="#">Standard 511.50.2987.001.49.1502</a>	? 99.84
<a href="#">Rollix2 1415</a>	? 94.69
<a href="#">Standard 5192.32.3150.990.41.1502</a>	? 146.50
<a href="#">Rollix1 141</a>	? 26.95
<a href="#">Standard 5191.50.3150.990.41.1502</a>	? 102.57
<a href="#">Rollix7 1606 02</a>	? 3.69
<a href="#">Standard 5191.40.3150.990.41.1502</a>	? 178.18
<a href="#">Rollix2 1565 02</a>	? 101.69
<a href="#">Standard 5191.32.3150.990.41.1502</a>	? 111.54
<a href="#">Rollix6 1595 04</a>	? 167.93
<a href="#">Standard 511.40.3150.000.11.1502</a>	? 174.74
<a href="#">Rollix1 1595</a>	? 126.13
<a href="#">Standard 511.40.3150.001.41.1502</a>	? 169.28
<a href="#">Rollix2 1715</a>	? 123.30
<a href="#">Standard 511.50.3167.001.49.1502</a>	? 179.81

<a href="#">Rollix1 1712</a>	? 101.01
<a href="#">Standard 512.40.3300.001.41.1502</a>	? 107.21
<a href="#">Rollix7 1830 04</a>	? 161.40
<a href="#">Standard 512.40.3300.000.11.1502</a>	? 172.30
<a href="#">Rollix6 1790 09</a>	? 51.85
<a href="#">Standard 512.45.3400.100.19.1502</a>	? 68.81
<a href="#">Rollix2 1805 02</a>	? 197.15
<a href="#">Standard 512.45.3400.101.49.1502</a>	? 63.40
<a href="#">Rollix1 1895</a>	? 48.43
<a href="#">Standard 5192.50.3550.990.41.1502</a>	? 186.16
<a href="#">Rollix7 1997 04</a>	? 7.60
<a href="#">Standard 511.50.3347.001.49.1502</a>	? 98.43
<a href="#">Rollix1 1845 02</a>	? 177.57
<a href="#">Standard 5192.32.3550.990.41.1502</a>	? 39.39
<a href="#">Rollix2 2022</a>	? 93.88
<a href="#">Standard 5192.40.3550.990.41.1502</a>	? 129.66
<a href="#">Rollix6 2002</a>	? 147.25
<a href="#">Standard 512.50.3520.001.49.1502</a>	? 189.44
<a href="#">Rollix2 204</a>	? 121.73
<a href="#">Standard 5191.50.3550.990.41.1502</a>	? 154.20
<a href="#">Rollix1 2040 03</a>	? 109.83
<a href="#">Standard 5191.40.3550.990.41.1502</a>	? 173.24
<a href="#">Rollix1 213</a>	? 79.43
<a href="#">Standard 5191.32.3550.990.41.1502</a>	? 123.47
<a href="#">Rollix6 2242</a>	? 14.48
<a href="#">Standard 5121.32.3550.990.41.1502</a>	? 63.15
<a href="#">Rollix2 2202</a>	? 60.76
<a href="#">Standard 511.50.3567.001.49.1502</a>	? 57.16
<a href="#">Rollix1 2202</a>	? 16.45
<a href="#">Standard 512.50.3739.001.49.1502</a>	? 179.34
<a href="#">Rollix7 24</a>	? 42.76
<a href="#">Standard 512.50.3839.001.49.1502</a>	? 153.45
<a href="#">Rollix6 2500 01</a>	? 17.97
<a href="#">Standard 5121.32.3750.990.41.1502</a>	? 200.38
<a href="#">Rollix2 2618</a>	? 84.01
<a href="#">Standard 5192.50.4000.990.41.1502</a>	? 8.96
<a href="#">Rollix1 2560 01</a>	? 2.50
<a href="#">Standard 511.50.3747.001.49.1502</a>	? 176.53
<a href="#">Rollix2 256</a>	? 102.42
<a href="#">Standard 5192.40.4000.990.41.1502</a>	? 79.54
<a href="#">Rollix7 2810 09</a>	? 34.96
<a href="#">Standard 5192.32.4000.990.41.1502</a>	? 198.55
<a href="#">Rollix6 2810 09</a>	? 117.70
<a href="#">Standard 5191.50.4000.990.41.1502</a>	? 47.28
<a href="#">Rollix1 3031</a>	? 19.35
<a href="#">Standard 5191.40.4000.990.41.1502</a>	? 77.47

<a href="#">Rollix2 3074 01</a>	? 37.02
<a href="#">Standard 5191.32.4000.990.41.1502</a>	? 70.90
<a href="#">Franke68552A</a>	? 127.12
<a href="#">Standard 5121.36.4000.990.41.1502</a>	? 114.12
<a href="#">Franke75061A</a>	? 126.16
<a href="#">Standard 5121.32.4000.990.41.1502</a>	? 153.13
<a href="#">Franke68733A</a>	? 42.00
<a href="#">Standard 511.50.4140.001.49.1502</a>	? 177.41
<a href="#">Franke71041A</a>	? 32.75
<a href="#">Standard 5121.36.4250.990.41.1502</a>	? 187.81
<a href="#">Franke68460A</a>	? 71.42
<a href="#">Standard 5121.32.4250.990.41.1502</a>	? 96.15
<a href="#">Franke68739A</a>	? 143.51
<a href="#">Standard 5192.50.4500.990.41.1502</a>	? 154.55
<a href="#">Franke68649A</a>	? 153.75
<a href="#">Standard 5192.40.4500.990.41.1502</a>	? 189.90
<a href="#">Franke68637A</a>	? 13.57
<a href="#">Standard 5191.50.4500.990.41.1502</a>	? 111.18
<a href="#">Franke75034A</a>	? 39.27
<a href="#">Standard 5191.40.4500.990.41.1502</a>	? 21.69
<a href="#">Franke66184L</a>	? 63.10
<a href="#">Standard 5121.40.4500.990.41.1502</a>	? 121.56
<a href="#">Franke73111L</a>	? 116.23
<a href="#">Standard 5121.36.4500.990.41.1502</a>	? 18.19
<a href="#">Franke68727A</a>	? 41.54
<a href="#">Standard 5121.40.4750.990.41.1502</a>	? 68.82
<a href="#">Franke73100L</a>	? 188.06
<a href="#">Standard 5121.36.4750.990.41.1502</a>	? 151.99
<a href="#">Franke77320B</a>	? 132.58
<a href="#">Standard 5192.50.5000.990.41.1501</a>	? 4.86
<a href="#">Franke75035A</a>	? 79.07
<a href="#">Standard 5191.50.5000.990.41.1502</a>	? 193.25
<a href="#">Franke74090A</a>	? 155.68
<a href="#">Standard 5121.45.5000.990.41.1502</a>	? 30.01
<a href="#">Franke66194L</a>	? 187.55
<a href="#">Standard 5121.40.5000.990.41.1502</a>	? 75.06
<a href="#">Franke68729A</a>	? 15.30
<a href="#">Standard 5121.45.5300.990.41.1502</a>	? 55.37
<a href="#">Franke77280A</a>	? 168.79
<a href="#">Standard 5121.40.5300.990.41.1502</a>	? 118.69
<a href="#">Franke68564A</a>	? 180.70
<a href="#">Standard 5192.50.5600.990.41.1502</a>	? 65.74
<a href="#">Franke68605A</a>	? 182.89
<a href="#">Standard 5191.50.5600.990.41.1502</a>	? 38.55
<a href="#">Franke77260A</a>	? 60.61
<a href="#">Standard 5121.50.5600.990.41.1502</a>	? 19.02



<a href="#">Franke68554A</a>	? 118.98
<a href="#">Standard 5121.45.5600.990.41.1502</a>	? 14.79
<a href="#">Franke68532A</a>	? 89.33
<a href="#">Standard 5121.50.6000.990.41.1502</a>	? 48.81
<a href="#">Franke73101L</a>	? 92.49
<a href="#">Standard 5121.45.6000.990.41.1502</a>	? 137.80
<a href="#">Franke66167L</a>	? 92.62
<a href="#">Standard 5192.50.6300.990.41.1502</a>	? 30.25
<a href="#">Franke68314A</a>	? 17.72
<a href="#">Standard 5191.50.6300.990.41.1502</a>	? 48.76
<a href="#">Franke75022A</a>	? 18.05
<a href="#">Standard 5192.50.6735.990.41.1502</a>	? 189.52
<a href="#">Franke68675A</a>	? 47.52
<a href="#">Standard 5121.50.6700.990.41.1502</a>	? 1.94
<a href="#">Franke77286A</a>	? 42.31
<a href="#">Standard 5191.50.6735.990.41.1502</a>	? 191.45
<a href="#">Franke74112A</a>	? 3.99
<a href="#">Rollix1 0181 02</a>	? 16.77
<a href="#">Franke68468A</a>	? 186.88
<a href="#">Rollix8 0220 05</a>	? 131.14
<a href="#">Franke66165L</a>	? 118.36
<a href="#">Rollix3 0217</a>	? 181.92
<a href="#">Franke66388L</a>	? 123.70
<a href="#">Rollix1 0235</a>	? 169.19
<a href="#">Franke73137L</a>	? 162.18
<a href="#">Rollix2 0245</a>	? 139.32
<a href="#">Franke68959A</a>	? 168.28
<a href="#">Rollix3 026</a>	? 95.33
<a href="#">Franke73112L</a>	? 196.81
<a href="#">Rollix8 0270 04</a>	? 36.83
<a href="#">Franke68793A</a>	? 49.94
<a href="#">Rollix1 0289 06</a>	? 47.45
<a href="#">Franke73034L</a>	? 103.21
<a href="#">Rollix2 0308 01</a>	? 155.58
<a href="#">Franke77305B</a>	? 58.26
<a href="#">Rollix6 0307</a>	? 42.55
<a href="#">Franke68524A</a>	? 10.35
<a href="#">Rollix8 0307</a>	? 178.20
<a href="#">Franke73047L</a>	? 69.08
<a href="#">Rollix8 0340 04</a>	? 60.67
<a href="#">Franke77202B</a>	? 181.37
<a href="#">Rollix3 0342 05</a>	? 18.85
<a href="#">Franke66402L</a>	? 140.92
<a href="#">Rollix3 036</a>	? 188.79
<a href="#">Franke74170A</a>	? 91.46
<a href="#">Rollix1 0342</a>	? 24.02

<a href="#">Franke68967A</a>	? 158.66
<a href="#">Rollix7 0380 01</a>	? 69.91
<a href="#">Franke68526A</a>	? 168.11
<a href="#">Rollix23 0411 01</a>	? 55.11
<a href="#">Franke73094L</a>	? 162.21
<a href="#">Rollix26 0411 01</a>	? 186.58
<a href="#">Franke74110A</a>	? 54.31
<a href="#">Rollix29 0411 01</a>	? 51.88
<a href="#">Franke74092A</a>	? 179.13
<a href="#">Rollix21 0411 01</a>	? 36.96
<a href="#">Franke68504A</a>	? 77.04
<a href="#">Rollix24 0411 01</a>	? 165.90
<a href="#">Franke68568A</a>	? 58.85
<a href="#">Rollix27 0411 01</a>	? 153.19
<a href="#">Franke77282A</a>	? 92.06
<a href="#">Rollix8 04</a>	? 98.17
<a href="#">Franke66149L</a>	? 165.39
<a href="#">Rollix6 04</a>	? 85.55
<a href="#">Franke68470A</a>	? 38.46
<a href="#">Rollix2 0422</a>	? 6.46
<a href="#">Franke67511A</a>	? 70.05
<a href="#">Rollix1 0422 01</a>	? 111.18
<a href="#">Franke73028L</a>	? 176.24
<a href="#">Rollix32 0411 01</a>	? 94.66
<a href="#">Franke68314B</a>	? 27.64
<a href="#">Rollix35 0411 01</a>	? 46.99
<a href="#">Franke74074A</a>	? 162.41
<a href="#">Rollix38 0411 01</a>	? 182.11
<a href="#">Franke68506A</a>	? 14.65
<a href="#">Rollix22 0411 01</a>	? 86.26
<a href="#">Franke71049A</a>	? 148.58
<a href="#">Rollix25 0411 01</a>	? 167.50
<a href="#">Franke66142L</a>	? 113.79
<a href="#">Rollix28 0411 01</a>	? 177.72
<a href="#">Franke66152L</a>	? 180.83
<a href="#">Rollix3 0402</a>	? 123.09
<a href="#">Franke74096A</a>	? 162.68
<a href="#">Rollix8 0405 05</a>	? 45.64
<a href="#">Franke66182L</a>	? 192.05
<a href="#">Rollix33 0411 01</a>	? 130.04
<a href="#">Franke77264B</a>	? 3.29
<a href="#">Rollix36 0411 01</a>	? 142.24
<a href="#">Franke71037A</a>	? 25.39
<a href="#">Rollix39 0411 01</a>	? 61.97
<a href="#">Franke77262A</a>	? 53.81
<a href="#">Rollix31 0411 01</a>	? 17.36

<a href="#">Rollix34 0411 01</a>	? 52.66
<a href="#">Rollix37 0411 01</a>	? 50.06
<a href="#">Rollix8 0475 08</a>	? 155.00
<a href="#">Rollix6 0475 22</a>	? 92.32
<a href="#">Rollix7 0489 11</a>	? 48.90
<a href="#">Rollix6 0508</a>	? 45.51
<a href="#">Rollix2 052</a>	? 197.98
<a href="#">Rollix3 0525 01</a>	? 101.18
<a href="#">Rollix23 0541 01</a>	? 193.85
<a href="#">Rollix26 0541 01</a>	? 139.29
<a href="#">Rollix29 0541 01</a>	? 94.51

## ZKL : Manish Bearing Enterprises

Also, ZKL is the biggest manufacturer of large-scale spherical-roller, special and split bearings in Central Europe. ZKL continuously improves technology (by ...

## ZKL PRICE LIST india 2013 - zip

RECOMMENDED RUPEE PRICE LIST- INDIA- 2013. BEARING DESIGNATION. Price In INR.  
BEARING DESIGNATION. Price In INR. 02474/02420 ZKL. 677. 1207 K C3 NEW FORCE.

## zkl bearings (india) private limited - The Economic Times

The fourth day had seen seven rounds of bidding, with the per unit price of the 1800 MHz band

increasing by 49% over its base price, to Rs135.6 crore for UP ( ...

## **Maximum retail price list**

Apr 1, 2018 — Maximum retail price list. Effective from. 1st July, 2018. For SKF domestic industrial products –. Spherical roller bearings and cylindrical ...

## **ZKL Archives - BEARING NEWS**

ZKL railway bearings production · BearingNews - April 2, 2019 ... ZKL launched a new cylindrical roller bearings with the optimized NEW.

## **ZKL MRP Pricelist 2011 | PDF | Consumer Goods - Scribd**

This is the current effective ZKL Bearings MRP List in India. Rates are in INR. contact [nitinbearings@gmail.com](mailto:nitinbearings@gmail.com) for discount structure.

## **ZKL Ball Bearings Wholesale Trader from New Delhi**

ZKL Bearings. ZKL Bearings. Approx. Rs 600 / Piece · 15-20 gm ; ZKL Ball Bearings. ZKL Ball Bearings. Approx. Rs 250 / Piece · Ball Bearing ; ZKL Industrial Bearing ...